MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

DATE OF PREP.

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

1-13-78

Section I

MANUFACTURERS NAME U. S. Paint Lacquer & Chemical Company

DMS 2112-7804 Ty.I, CLASS I

2101 Singleton Street

CITY, STATE, AND ZIP CODE

St. Louis, Missouri 63103

EMERGENCY TELEPHONE NO.

(314)621-0525

PRODUCT CLASS

TRADE NAME

Aliphatic Polyurethane

BLACK GLOSS

Alumigrip Black Enamel

MANUFACTURERS CODE IDENTIFICATION

92-B-1-C

Catalyzed 1 to 1 By

Volume with 92-C-3*

Section II — HAZARDOUS INGREDIENTS

INGREDIENT	Volume PERCENT	РРМ ,	TLV mg/M³	LEL	VAPOR PRESSURE in mm Hg
Methyl Toluer Xylend 2-Etho	18.8 19.4 13.5 3.1 45.2	400 200 100 100 100	1440 590 375 435 540	2.2 1.8 1.27 1.1 1.7	20° C 76.0 71.2 38.0 9.5 1.2

Section III — PHYSICAL DATA

BOILING RANGE	167	to	329°F.	

VAPOR DENSITY

X HEAVIER

LIGHTER, THAN AIR

EVAPORATION RATE

FASTER

SLOWER, THAN ETHER

PERCENT VOLATILE 62.8 **WEIGHT PER** GALLON

8.76

Section IV — FIRE AND EXPLOSION HAZARD DATA

Combustible Liquid 100°F.-200°F.

DOT CATEGORY Flammable Liquid 20°F.-100°F.

FLASH POINT

46° F. T.C.C.

LEL 1.1

Non Flammable

extinguishing MEDIA Dry chemical or foam

UNUSUAL FIRE AND EXPLOSION HAZARDS Do not expose to spark or open flame

ecial fire fighting procedures Personnel who are fighting isocyanate fires should wear self-contained breathing apparatus.

Section V — HEALTH HAZARD DATA	
THRESHOLD LIMIT VALUE 100 TO 400 PPM EFFECTS OF OVEREXPOSURE Eye & upper respiratory irritant	
EMERGENCY AND FIRST AID PROCEDURES If exposed to excess vapor, remove to fresh air and seek mediatention. If splashed on skin or in eyes, flush with large amounts of water and seek immediate medical attention.	.cal
Section VI — REACTIVITY DATA	
STABILITY UNSTABLE X STABLE CONDITIONS TO AVOID Excess heat and/or oxidizing me incompatability (Materials to avoid) Avoid contact with water, alcohol hazardous decomposition products amines, and other compounds which react with isocyanates. HAZARDOUS POLYMERIZATION MAY OCCUR WILL NOT OCCUR CONDITIONS TO AVOID	aterials
Section VII — SPILL OR LEAK PROCEDURES	
compound and then material placed in a tightly container. WASTEDISPOSAL METHOD In accordance with local, state, and federal environmental control regularies. Section VIII — SPECIAL PROTECTION INFORMATION	
RESPIRATORY PROTECTION Bureau of Mines approved mask for removal of particulate matter and ch base for removal of solvent vapor.	arcoal
VENTILATION Sufficient to keep air supply above threshold limit values.	
PROTECTIVE GLOVES Rubber or Plastic EYE PROTECTION Goggles	
OTHER PROTECTIVE EQUIPMENT Hypersensitive persons should use protective creams.	
Section IX — SPECIAL PRECAUTIONS PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Keep away from heat, sparks and flames.	
OTHER PRECAUTIONS	
	•